

Fig.1




Fig.2




Fig.3




Fig.4




Fig.5





Fig.6







Fig.7

Fig.8







Fig. 11





Fig. 12



0978729-031501


Fig. 13



Fig. 14






Fig. 15






T09T50-0202400

Fig. 16



092329-064601

Fig. 17



109T50" 62282260

Fig.18







Fig.19





Surface of III-V Compound Compositionally Graded Layer After Epitaxy

FIG. 10A



Surface of III-V Compound Compositionally Graded Layer After Epitaxy and Planarization

FIG. 10B